



State of Utah

Department of
Natural Resources

Division of
Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

March 4, 2004

TO: File

FROM: Paul Baker, Senior Reclamation Biologist

SUBJECT: Site Inspection, Jon Young, Torrey Buff Quarry, S/055/012, Wayne County, Utah

Date of Inspection: January 30, 2004
Time of Inspection: About 2:10 to 2:20 p.m.
Conditions: Mostly cloudy, 40's, patchy snow
Participants: Will Stokes (SITLA) and Paul Baker (DOGM)

Purpose of Inspection:

We were in the area and wanted to check the site.

Getting to the site:

Directions to the site are in the report for the December 13, 2002, inspection, and these directions work.

Observations:

The site is shown in Photos 1 through 3. The site has changed little in the past year, but I do believe there has been some mining activity. In the last inspection, there was some palletized stone, but there was none during the current inspection.

Conclusions and Recommendations:

I stated in the report for the previous inspection that the operator should begin salvaging topsoil. Although there is no soil stockpile, I don't know that the operator has disturbed any new areas. Soil should be salvaged if any new areas are disturbed.

PBB:jb

cc: Jon Young, Operator
Will Stokes, SITLA

O:\M055-Wayne\S0550012-TorreyBuff\inspections\ins-01302004.doc

ATTACHMENT

Photographs

S/055/012, Torrey Buff Quarry, Jon Young

Inspection Dated: January 30, 2004; Report Dated: March 4, 2004



Photo 1



Photo 3



Photo 2